

Memorandum

To:

Jeff Montera, Project Manager

From:

Angela Frandsen, Quality Assurance Manager

ahf

Reviewed by:

Krista Lippoldt, Quality Assurance Coordinator for EPA

Region VIII RAC

Date:

December 20, 2002

Subject:

Libby CSS QAM checklist for 11/3/02 to 11/22/02

The following summarizes the QA activities that are being verified biweekly by the QAM for the Libby CSS. These activities are discussed in Section 7 of the CSS Final SAP. This memorandum covers the above–referenced final three weeks of the field season.

1. Field Team Orientation

(QAM will attach the signature page for each orientation)

Number of new field team members: 0

Number of field team member orientations: 0

2. Field Form Completion Checks (IFFs and FSDSs)

(QAM will perform a 10% check on completed field forms sent to Helena for evidence that field team members are doing the required QC checks.)

Number of IFFs completed: 149 between 10/20 and 11/2/02

Number of IFFs received in Helena: 149

Number and percent of IFFs checked by the QAM for completeness and correctness:

17 (11.4%); 4 IFFs found with problems.

Corrective Action: See attached list of corrective actions.

Number and percent of IFFs checked by the CSS task leader for completion and correctness: 149, 100%

Libby CSS QAM Checklist December 20, 2002 Page 2

Number of FSDSs completed: 175 between 10/20 and 11/2/02

Number of FSDSs received in Helena: 198 (FSDSs shipped to Helena would include those from 11/18 to 11/22 because they are shipped on Fridays, which accounts for the higher total)

Number and percent of FSDSs checked by the QAM for completeness and correctness: 23 (11.6%); no problems found.

Corrective Action Taken: None required

Number and percent of FSDSs checked by the CSS task leader for completion and correctness: 175, 100%

Comment:

3. Supplemental Verification of Vermiculite Product

(CSS field team leader to notify QAM by email if this occurs)
Number of occurrences of supplemental verification: None
Addresses of verifications: NA

4. Screening Field Checks

(CSS task leader will check 2% of all properties)

Total number of properties sampled through 11/22/02: 3123

Total number and percent of screening field checks performed by task leader: 15 checks during this three week time period; 69 (2.2%) properties have been checked overall.

Comment: Number of screening field checks exceeds 2%

5. Field Audits

Field audit conducted when and by whom? None

6. Field QC Samples

Field Duplicates (1/20)

Number of field samples collected: <u>320</u> Number of duplicates collected: <u>19</u>

Ratio: 1.19/20

Equipment Blanks (1/day)

Number of days soil sampling occurred: <u>13</u> Number of equipment blanks collected: <u>12</u>

Ratio: 0.92/day

Aqueous Rinsates (1/day, 3 different weeks throughout field season) Number of days expected to collect rinsates during the time frame: 0 Number of rinsates collected: 0

Ratio: NA

Next time period rinsates expected to be collected: <u>No additional rinsates to be</u> collected during this field season

Total number of rinsates collected since sampling began: 18 for CSS and 1 for Stimson Lumber sampling

Comment: Field team inadvertently did not collect equipment blank on 11/16/02.

This deficiency was not identified until after the field season ended, therefore, no corrective action could be taken.

Preparation Duplicates (1/20)

Number of samples prepared by the CDM laboratory: 450 dried

Number of preparation duplicates collected: 24

Ratio: <u>1.07/20</u>

Preparation Blanks (1/day)

Number of days that samples were prepared by the CDM laboratory: 14

Number of preparation blanks collected: 4

Ratio: 1/batch created

Comment: <u>T. Burgesser noted that he only prepared one preparation blank per batch,</u> rather than one preparation blank per day.

SEM/IR Splits (first 500 samples: 1/5 of IR $\leq 0.5\%$, 1/10 of IR > 0.5% and $\geq 1\%$)

Total number of samples ≤ 0.5%: None yet

Number and percent of SEM/IR splits: None yet

Total number of samples > 0.5% and $\geq 1\%$: None yet

Number and percent of SEM/IR splits: None yet

Comment: No laboratory yet under contract to perform IR soil analysis. Anni Autio (laboratory coordinator) in charge of arranging this once laboratory is subcontracted.

7. Data Entry Checks (10% of Volpe data entry)

Number of data entries: None (no analytical results)

Number and percent of data entries checked: <u>None (no analytical results – data entry</u> to be checked after analytical <u>data</u> are uploaded into database)

Name of person(s) checking data entries: NA at this time

Libby CSS QAM Checklist December 20, 2002 Page 4

8. Data Validation

Number of samples validated and reviewed and by whom: None, no analytical results yet

Number of sample results rejected: 0 out of 0

9. CDM Document Review

Documents issued to the client: <u>Work Plan Revision 2, November 6, 2002</u>
Which ones required Editorial Review and was review conducted? <u>Work Plan,</u>
Editorial Review not conducted

Which ones required Technical Review and was review conducted? Work Plan, Yes Which ones required QA review and was review conducted? Work Plan, Yes

Field Record of Deviation/Request for Modification forms completed and sent to EPA for approval: Form 000062, Change to Soil Sample Preparation Method

Overall Comments: This is the final memorandum focusing on CSS field activities. Future memoranda will be revised to focus on data validation and data entry activities.

cc: Jim Christiansen, EPA
Mary Goldade, EPA
Mark Raney, Volpe
Krista Lippoldt, CDM
Dee Warren, CDM
Dave Schroeder, CDM
Terry Keller, CDM
George DeLullo, CDM
Tim Wall, CDM

IFFs that need to be corrected:

Period: Paperwork received for 11/3/02 through 11/23/02

IFF BD#'s	10% QC Check problem found	Corrective Action Taken	Date Corrected
BD-002758	Owner stated that LV from old pumphouse was dumped by the gravel pad when the pumphouse was taken down. This is only noted in the logbook notes and on the property sketch. This information needs to be noted in the IFF.	CSS TL noted in additional comments field	11/22/2002
BD-002960	Logbook notes that tenant stated that LVAI was removed from the attic by the owner prior to her moving in. On page 5 the question, "Did the attic ever have ZAI?" is answered as "unknown".	Answer changed to YES by CSS TL	11/22/2002
BD-003048	BD-003048 Page 2 - Years at current location is not circled	>15 circled by CSS TL	11/22/2002
BD-003061	LV was observed by the soil team on 11/2/02. The IFF BD-003061 exposure assessment should be changed accordingly to reflect some exposure.	IFF changed by CSS TL	11/22/2002

ted:
rrec
00
o P
ed t
ne
that
DSs
FSI

Paperwork received for 11/3/02 through 11/23/02

Period:

1
p
ms foun
No problems found

Address: 1590 F 57 ST. EXT.

Data Item		Value	Notes		
CONTAMINANT SCREENING STUDY ASSESSMENT					
	Occi	pant information			
is there any knowledge of former miners, close relative of miners, or any highly exposed persons living or visiting the property?	Yes Unknown	6			
is the resident, past or present, diagnosed with an aspestos related disease?	Yes Unknown	(No.)			
	Ind	oor information			
Does the Interior have Zonolite attic insulation?	Yes Unknown	©			
Did the interior ever have Zanolite attlc insulation?	Yes Unknown	⊗ NA	NA applies if attic currently has ZAI.		
Are there vermiculite additives in any of the building materials?	Yes Unknown	0			
	Outdoor Information				
is there any evidence of primary source materials at or near the property?	Yes Unknown	0			
Could this have been tracked indoors or otherwise spread outdoors on the property?	Yes Unknown	6	·		
Overall Assessment					
Are primary source materials present at the property?	Yes	®			
Where are primary source materials located?	Inside Both	Outside (NA)			
ADDITIONAL INFORMATION 11/22/02 D Olymped by the gravel pad u by field team.		stated that LV to	rom old pumphouse was		



Address:	152 Woodland	Rd.	#7	
	_			

Data Item		Value	- Notes	
Contaminant screening study assessment				
	Occupa	nt Information		
Is there any knowledge of former miners, close relative of miners, or any highly exposed persons living or visiting the property?	Yes	No		
Is the resident, past or present, diagnosed with an asbestos related disease?	Yes Unknown	No	Not screened	
	Indoor	Information		
Does the Interior have Zonolite attic insulation?	Yes Unknown	No		
Did the interior ever have Zonolite attic insulation?	Unknown Quil-22	No NA ⇔ĭ	NA applies if attic currently has ZAI. See additional Connects	
Are there vermiculite additives in any of the building materials?	Yes Unknown	™		
	Outdoo	r information		
Is there any evidence of primary source materials at or near the property?	Yes Unknown	No	yard	
Could this have been tracked indoors or (otherwise spread outdoors on the property?	Pes Unknown	No		
Overall Assessment				
Are primary source materials present at the property?	Yes	No		
Where are primary source materials located?	Inside Both	Outside NA		
ADDITIONAL INFORMATION Res			erformed an as bestos	

Address: 190 WARDS PD.

Data Item	Value	Notes
OCCUPANT INFORMATION		
Number of Adults/Employees	0 1 2 3 4	
	5-15 16-20 21-30 >30	
Number of Children	0 1 2 3 4	
	Other:	
Years at Location	<1 1-5 5-10 10-15 >15 Dia 11-32-02	Since 1945
Was the residence/bullding remodeled?	Yes No	
	If yes,	
·	When (years): <2 2-5 >5	
	Where: Attic Living Areas	
	Garage Basement	
	Other:	
Has resident/business purchased any Libby vermiculite materials from W.R. Grace in the past?	Yes (No)	BUT, DID HAUL LU IN THE PAST
Has the property at this location been used for a for-profit enterprise of distributing, treating, storing, or disposing of Libby vermiculite?	Yes No	
Are there any known areas of exposed	Yes (No) -	
varmiculite?	If yes,	,
	Where: Ceiling Walls	
	Floors Attic	
·	Other:	

Address: 309 PINEWOOD LN

BD# 00306/

Data Item	Value	Nates		
CONTAMINANT SCREENING STUDY AS	SSESSMENT			
	Occupant Information			
Is there any knowledge of former miners, close relative of miners, or any highly exposed persons living or visiting the property?	Yes No Unknown			
Is the resident, past or present, diagnosed with an aspestos related disease?	Yes No Unknown	·		
	indoor information			
Does the interior have Zonolite attic insulation?	Yes (Ng/ Unknawn			
Did the interior ever have Zonolite attic insulation?	Yes No Unknown NA	NA applies if attic currently has ZAI.		
Are there vermiculite additives in any of the building materials?	Yes No Unknown			
Outdoor Information				
is there any evidence of primary source (materials at or near the property?	Yes No DW 11-22-02-			
Could this have been tracked indoors or otherwise spread outdoors on the property?	Yes DC 11.22.02			
Overall Assessment				
Are primary source materials present at the property?	Yas Ne 112202			
Where are primary source materials located?	Both Outside Outside			
ADDITIONAL INFORMATION				

Address: 309 PINEWOOD LN

Data Item	Vali	ne	Notes
EXPOSURE ASSESSMENT			
Type and Frequency of Activity Near	Frequency:	Once a day	Not Applicable applies when no
Vermiculite Material - Indoor		Once a week	vermiculite is present on the property.
		Once a month	
•		Once a year	
		Not Applicable	
	Duration of Contact:	<1 hour	
·		1-2 hours	
		2-4 hours	·
		>4 hours	
·		Not Applicable	,
	Extent of Contact:	Heavy	
		Moderate	
	į	Light	
		Not Applicable	
Type and Frequency of Activity Near Vermiculite Material - Outdoor	Frequency:	Once a day	Not Applicable applies when no vermiculite is present on the property.
VEHINGUIRE MEIGHAI - CUMBO		Once a week	veilulente is present on the property.
		Once a month	
		Once a year	YU 11-22-02
		Not Applicable	11.22.02
•	Duration of Contact:	<1 hour	
•		1-2 hours	
		2-4 hours	
		>4 hours	- DW
-		Not Applicable	11.22.06
(Extent of Contact:	Heavy	
		Moderate	
		Light.	
**************************************		Not Apaticable	10.22.00

CSS Task Leader Screening Field Checks (2% checks) for 11/3/02 - 11/23/02

BD Number	Address	Discrepancy and Corrective Action
BD-002828	76 Alpine Way	No Issues
BD-002540	1705 Farm to Market Rd	Question 2 on Pg 5 was changed from no to unknown as the resident was not tested for an asbestos disease and was not able to say for sure the answer is NO
BD-002610	1312 Montana Ave	Additional vermiculite was observed outdoors and addition made to field sketch
BD-002578	293 Taylor Rd	Question 2 on Pg 5 was changed from no to unknown as the resident was not tested for an asbestos disease and was not able to say for sure the answer is NO
BD-002915	985 Farm to Market Rd	No issues
BD-002536	1704 Farm to Market Rd	No issues
BD-002662	95 Sunny Side Dr	Page 2 Number of Children changed to 2. Two grandchildren visit frequently. Page 2 Purchased vermiculite changed to no. Material was not purchased but obtained for free
BD-002663	125 Sunny Side Dr	Page 2 Number of Children change to 2. Two Nephews visit.
BD-002771	2292 Farm to Market Rd	No issues
BD-002847	565 Terrace View Rd	Presence of vermiculite was missed in yard
BD-003003	251 A Cedar Meadow Rd	No issues
BD-002772	782 Farm to Market Rd	Answers to Outdoor Information questions were changed to NO
BD-002904	151 Lodge Pole Way	Knowledge of former Miners changed to YES
BD-003000	127 Lodge Pole Way	Knowledge of former Miners changed to YES
BD-002667	119 Evans Rd	No issues

55: 1765 Form to Murket Ad.

Data Item	Value	Notes		
CONTAMINANT SCREENING STUDY ASSESSMENT				
	Occupant Information			
is there any knowledge of former miners, close relative of miners, or any highly exposed persons living or visiting the property?	Yes No Unknown Soully 102			
is the resident, past or present, diagnosed with an asbestos related disease?	Yes Na Vinknown	Resident has not been screened		
	indoor information			
Does the Interior have Zonolite attic insulation?	Yes No.			
Did the interior ever have Zonolite attic Insulation?	Yes No Unknown NA	NA applies if attic currently has ZAI.		
Are there vermiculite additives in any of the building materials?	Yes No Unknown			
Outdoor Information				
Is there any evidence of primary source materials at or near the property?	Yes No. Unknown			
Could this have been tracked indoors or otherwise spread outdoors on the property?	Yes No.			
Overali Assessment -				
Are primary source materials present at the property?	Yes No.			
Where are primary source materials located?	Inside Outside Both NA			
ADDITIONAL INFORMATION House was originally locatedat the Stimson Lumber Mill.				

P.3/5

SS INFORMATION FIELD FORM (continued)

Address: 1312 Maintana AVE

BD# C02610

Data (tem	Value	Notes
CONTAMINANT SCREENING STUDY AS	SSESSMENT	·
	Occupant Information	
Is there any knowledge of former miners, close relative of miners, or any highly exposed persons living or visiting the property?	Yes No Unknown	
is the resident, past or present, diagnosed with an asbestos related disease?	Yes No Unknown	
	indoor information	
Does the interior have Zonolite attic insulation?	Yes No Unknown	
Did the Interior ever have Zonolite attic Insulation?	Yes No Unknown NA	NA applies if attic currently has ZAI.
Are there vermiculite additives in any of the building materials?	Yes No Unknown	IN Masonry in cion 15
	Outdoor Information	
Is there any evidence of primary source (materials at or near the property?	Yes No Unknown	
Could this have been tracked Indoors or (otherwise spread outdoors on the property?	Yes No Unknown	· _
	Overall Assessment	
Are primary source materials present at the property?	Yes No	
Where are primary source materials located?	Both) NA	in petic
ADDITIONAL INFORMATION NO	Dog ZAI in Attic. LV in	garden

1312 Montana Ave

BD# 00 26/0

FIELD DIAGRAM OF PROPERTY

Identify important features (i.e. drainage, trees, gardens, structures, flowerbeds, utility poles, known underground

NOT TO SCALE

utilities, suspected Libby amphipole source areas, sample locations, etc). Include north arrow.

CSS Primary Structure (FF_V5.wpd

Page 6 of 7

9:49AM CDM

NO.954 P.2/5

SS INFORMATION FIELD FORM (continued)

Address: 293 Tuylor Rd

BD# 002578

Data Item	Value Notes				
CONTAMINANT SCREENING STUDY ASSESSMENT					
	Occupant	Information			
is there any knowledge of former miners, close relative of miners, or any highly exposed persons living or visiting the property?	Yes Unknown	ND 11/14/02			
is the resident, past or present, diagnosed with an aspestos related dispase?	Yes Unknown	A	Resident has not been tooked to		
	Indoor Ir	formation			
Does the interior have Zonolite attic insulation?	Yes C	No	•		
Did the Interior ever have Zonolite attic insulation?	Yes (Unknown	NO NA	NA applies if attic currently has ZAI.		
Are there vermiculite additives in any of the building materials?	Yes (Unknown	100	NOKE OBSERVED		
	Quidoqr i	nformation			
Is there any evidence of primary source materials at or near the property?	Yes · (No.			
Could this have been tracked indoors or otherwise spread outdoors on the property?	Yes (No			
	Overall As	sessment	•		
Are primary source materials present at the property?	Yes (NO			
Where are primary source materials located?	Inside Both	Outside NA			
ADDITIONAL INFORMATION TWO NICE DOGS - BRING BONES					

ί,

NO.979

P.3/4

०००७७०११

S INFORMATION FIELD FORM (continued)

Address: 45 SUNNYSIDE DR

3D# <u>485665</u>

Data Item	Value	Notes
OCCUPANT INFORMATION		
Number of Adults/Employees	0 ① 2 3 4	
	5-15 16-20 21-30 >30	
Number of Children	Other: 2 3 4	Grandchildren visit 2x per menth
Years at Location	<1 1-5 5-10 10-15 15	30 YEARS
Was the residence/building remodeled?	Yes No	ALL WALS & CETLINGS
	If yes, When (years): <2 2-5 55 Where: Attic Living Areas Garage Basement	
Has resident/business purchased any Libby vermiculite materials from W.R. Grace in the past?	Other No	Didnot purchase material, uses obtained for free and uses added to sa
Has the property at this location been used for a for-profit enterprise of distributing, treating, storing, or disposing of Libby vermiculite?	Yes No	
Are there any known areas of exposed vermiculite?	(Yes No	LUAT OBSERVED IN LIGHTET XTURES OF
j	Where: Cailing Walls	LIVING AREA
	Floors Attic	
	Other:	

NO.979 P.4/4

INFORMATION FIELD FORM (continued)

ddress: 125 SUNNY SIDE AVE

Data Item	Value	Notes
OCCUPANT INFORMATION	·	0
Number of Adults/Employees	0 1 2 3 4	
	5-15, 16-20 21-30 >30	
Number of Children	1 (2) 3 4 11/15/02 2	Ne pleus visit & 2x perges
Years at Location	<1 1-5 5-10 10-15 >15	16 YEARS
Was the residence/puilding remodeled?	Yes No	
	If yes,	
	When (years): <2 · 2-5	
	Where: Attic Living Areas	
·	Garage Basement	
·	Other	
Has resident/business purchased any Libby vermiculite materials from W.R. Grace in the past?	Yes No	
Has the property at this location been used for a for-profit enterprise of distributing, treating, storing, or disposing of Libby vermiculite?	Yes (ND	
Are there any known areas of exposed vermiculite?	Yes No	
Act Mirchite L	lf yes,	,
	Where: Ceiling Walls	
·	Floors Attic	-
	Other:	

Address: 565 Tecrace View Rd

Data Item	Value	Notes
INDOOR ASSESSMENT		
Vermiculite Insulation Past or Present	Attic: Yes O NA Unknown Walls: Yes O NA Unknown Basement: Yes No NA Unknown Crawl Space: Yes No NA Unknown Other:	Visual confirmation of current presence or absence required for attic. The Glass
Evidence of Physical Damage?	Yes No	
Evidence of Water Damage?	Yes (No	
OUTDOOR ASSESSMENT		
Libby Amphibale Saurces Present	Garden: (as No NA NA Yard: Yes) NO NA Stockpiles: (Yes) No NA Other.	baile yard.
Proximity to Other Properties with Potential Sources of Libby Amphiboles	Next door Within same block Other: Unknown	

CSS INFORMATION FIELD FORM (continued)

#3810/16/02

Address: 565 Terror Terrore View Rel

Data Item		Value	Notes
CONTAMINANT SCREENING STUDY A	SSESSMENT		
	Occu	pant Information	. PA. WOR
Is there any knowledge of former miners, close relative of miners, or any highly exposed persons living or visiting the property?	Yes Unknown	No PAA 10/14/02	the worked at saw mill for 30 years.
Is the resident, past or present, diagnosed with an esbestos related disease?	Yes Unknown	No '	notsereened.
	indo	oor Information	
Does the interior have Zonolite attic Insulation?	Yes , Unknown	(B)	
Did the interior ever have Zonolite attic insulation?	Yes Unknown	NO NA	NA applies if attic currently has ZAI.
Are there vermiculte additives in any of the building materials?	Yes Unknown	No	none observed
<u> </u>	Outd	oor Information	
Is there any evidence of primary source material at primary the property?	Yes Unknown	No ·	garden Flower beds & flower bedatheigh bors
Could this have been tracked indoors or otherwise spread outdoors on the property?	Ves Unknown	No	
	Over	all Assessment	
Are primary source materials present at the property?	(es)	No	flowerbed on Sside, borrow source pile Nside, large garden
Where are primary source materials located?	inside Both	Outside) NA	
ADDITIONAL INFORMATION_ NO T	50g5-13	aces of land	<u>.</u>

NOV. 18. 2002 6: 41PM CDM

CSS INFORMATION FIELD FORM (continued) NO.003 P.5/5 BD- 002847 Address: 565 Terrace View Rd 200 Identify important features (i.e. drainage, trees, gardens, structures, flowerbeds, utility poles, known underground utilities, suspected Libby amphibole source areas, sample locations, etc). Include north arrow. garden x NOTE O SCALE Page 6 of 7 CSS Primary Structure IFF_VS,wpd

NOV.18.2002

6:41PM

Address: 785 Few to Market Rd

6

Data Item	Value	Notes
CONTAMINANT SCREENING STUDY AS	SSESSMENT	
	Occupant Information	
is there any knowledge of former miners, close relative of miners, or any highly exposed persons living or visiting the property?	Yes No Unknown	worked on Ruil Road, current resident.
is the resident, past or present, diagnosed with an appestos related disease?	Ves No Unknown	rest of Comily - OK
	indoor information	
Does the interior have Zonolite attlc Insulation?	(Pes) No Unknown	APPROXIMATELY 625 ft 3
Did the interior ever have Zonolite attic insulation?	Unknown NA	NA applies if attic currently has ZAI.
Are there vermiculite additives in any of the building materials?	Yes No Unknown	hone objective d
	Outdoor Information	
Is there any evidence of primary source materials at or near the property?	Yes No No Unknown,	
Could this have been tracked indoors or otherwise spread outdoors on the property?	Yes (No) Unkparin 2: 1/20/05	
	Overall Assessment	
Are primary source materials present at the property?	Yes No	
Where are primary source materials located?	Inside Outside Both NA	
ADDITIONAL INFORMATION CAL. (log - seignozy	
290 chark performed 1/20 changes with inch to the I	clos: Nocation (Volume	red, and subsequent

Address: 151 Lodge Pole way

BD# <u>OO2999</u>

Data Item		Value	Notes	
CONTAMINANT SCREENING STUDY AS	SSESSMENT			
	Occup	eant information	2	
Is there any knowledge of former miners, close relative of miners, or any highly exposed persons living or visiting the property?	Yes) Unknown	(MG)	For ends isselfois. I and stayed for several weeks they worked at mine.	
Is the resident, past or present, diagnosed with an asbestos related disease?	Yes Unknown	(No)	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	
	indo	or Information		
Does the interior have Zonolite attic insulation?	Yes Unknown	No		
Did the interior ever have Zonolite attic insulation?	Yes Unknown	No No	NA applies if attic currently has ZA!,	
Are there vermiculite additives in any of the building materials?	Yes Unknown	No		
	Outdo	or Information		
Is there any evidence of primary source materials at or near the property?	Yes Unknown	No		
Could this have been tracked indoors or otherwise spread outdoors on the property?	Yes Unknown	(No		
	Overa	ll Assessment		
Are primary source materials present at the property?	Yes	(No)		
Where are primary source materials located?	Inside Both	Outside		
ADDITIONAL INFORMATION NO 17	ry's, Left	of Trailer Next	<i>रू इसहरू</i> लोगे १९३०	

Address 127 Lada Pale way

BD# <u>CO300</u>0

Data Item	Value	.	Notes		
CONTAMINANT SCREENING STUDY ASSESSMENT					
	Occupant Inform	nation il eclo	2		
Is there any knowledge of former miners, close relative of miners, or any highly exposed persons living or visiting the property?	Yes No		to work fit Grace and visited offen.		
is the resident, past or present, diagnosed with an asbestos related disease?	Yes No) }			
	indoor informa	tion			
Does the interior have Zonolite attic insulation?	Yes No				
Did the interior ever have Zonolite attic insulation?	Yes No NA Unknown NA		NA applies if attic currently has ZAI.		
Are there vermiculite additives in any of the building materials?	Yes No				
	Outdoor Informa	noiti			
Is there any evidence of primary source materials at or near the property?	Yes No		·		
Could this have been tracked indoors or otherwise spread outdoors on the property?	Yes No				
	Overall Assessm	ient			
Are primary source materials present at the property?	Yes No				
Where are primary source materials located?	Inside Outsid	2)			
ADDITIONAL INFORMATION ONE DE INSUE					

COMPEVERME TRUGRHID 3252-116-QC-REVU-15017

Libby Asbestos RI SAP

11/5/2002

CDM Faciani Fragrams Corpor QC Review Shoot-WP Rev. 2 3282-116-PP-

Quality Control Review Sheet

Charles Name: RAC		Projec	Nuncer.	328	2-116
Dogment Tree: Work Plan					
Dormer Tried Cock Plan Raisian 2/3282-116-PP-HKPN-15					
Initiated By: J. Monreeq	ter Carle Pipinai and an an air air a	Produ	a Lucion J	Mo	NTERA
Der faidered: 11/5/02		Date I	due in Client	11/16	2
QCC: FES Clans	,		il Duc Dese:	11/5/01	
Reviews Required				Document	Vassion
	tory Raylew	 	Brelining		
	Eng Raview		Wolcong Dr		- ,
TOCC Chief.			Final Drait		
QA*	to garden to the second		Final Docum	ent	
Estimated Review Educate Editorial:	. Testmirel		C	QA	Ragulatory ·
EngineeringOther		est ym			
"QA review is required for work plans, field	بالمحمدية والماد	२वाच, धा	८ ६००मान्यंद्र व	रक्ट्यांटडु क्ष्ट	imical services.
Editorial Roviowes:	Due Date	Dane Ra	viewsi .	Signame	
Repart Iran	. No Ciarge	•	See Text is	r Changes	Please Call to Discuss
Overall Organization :	. [1	
Format	Ū.	• . •	٠. د	3	
Clarity, Consistency, Granuser,		- 1] • •	, 0 ,
Reference Lin/Circuions					
Tebles/Figure		i		1	
QCC Confirmation of Cha	nges	, 🗓		, .	
Tachnical Reviews: Stens	Due Dage	Date Ra	Maraed .	Signature	Jungans um)
Report item	No Cranges		See Tear for		· Please Call to Discuss
Intended Scape Scatted	Q,	1			
Learnical Abediraci	. 0				
Calculations Checked					ū -
Tables/Figures Support Test		ŀ			
Conclusions Resembled	Q.	.]			
QCC Confirmation of Char	हेल	X			
Adrimonal Raylewar:	Date Review	ed:	Signamy		
	Otte: 11/5	•	K		
Mara Stateman		io augus			
CC Final Confirmation Signature:				Dar	= 11/6 or

000062



Record of Deviation/ Request for Modification

to the

Libby Sampling and Quality Assurance Project Plan
Field Activities

Instructions to Requester: Fax to contacts at bottom of form for review and approval.

File approved copy with Data Manager and fax copy to SRC.

	uracdad	, 11 Z6·6Z
Project QAPP (circle one):		(approval pending), c (approval pending)
	Phase I (approved 4/00) Phase	e II (approved 2/01)
•	Removal Action (approved 7/00)	SS (approval 5/02)
Scenario No. (circle one):	1 2 3 4 🖎	
Requester: Der W. Company: CDM	Jarren	Title: CSS Taskleader Date: 11:22:02
Description of Deviation:	de Preparation SOP	
Reason for Deviation:	ber deviation is documented on: 11	
Potential Implications of this D None. No adverse in	Deviation: Locals anticipated. Modific	ations to sop are documented.
Duration of Deviation (circle of Temporary Date(s):		
Permanent (comple	te Proposed Modification Section)	
Proposed Modification to SQA SQAPP when applicable): See Cottoched SOP	PP (attach additional sheets if nece	essary; state section and page numbers of
Technical Review: Volpe Project Manage	2 2 Control of designate)	Date: 11/23/02
iality Assurance Review and (Quality Assurance Cod	Approval: <u>SAUCHCU</u> ordinator or designate)	Date: 11/22/02
Approved By:	4 . 0. 004	